

Event Date	Operating Airline	Flight Number	Departure Airport	Arrival Airport	Aircraft Registration Number	Aircraft Type	Event Summary	Investigating Country (Investigating Authority)	Official Investigation Report by	Status of Company-Internal Investigation Committee
Jun 25,22	AKX	1626	KMJ	ITM	JA854A	DHC-8-400	NH1626 encountered a strong tremor during the flight, so the belt sign was turned on. After that, the shaking subsided, and when I checked the situation inside the cabin, the cabin attendant who was working in the rear galley fell and hit his waist against the floor and was injured. After arriving at Itami Airport, he was diagnosed with a sacral fracture.	Japan JTSB	Report published on October 26, 2023	"Investigation committee dissolved on November 30, 2023