

Event Date	Operating Airline	Flight Number	Departure Airport	Arrival Airport	Aircraft Registration Number	Aircraft Type	Event Summary	Investigating Country (Investigating Authority)	Official Investigation Report by Investigating Authority Source: JTSB Homepage	Status of Company-Internal Investigation Committee
November 29, 2013	AKX	4915	Fukuoka	Fukue	JA462A	DHC-8-400	During approach to Fukue Airport, the aircraft was struck by lightning at around 5,300 ft about 20 km northeast of the airport. The aircraft sustained damage from the strong impact due to the lightning discharge.	Japan JTSB	Report published on April 23, 2015	Investigation committee not established