

Event Date	Operating Airline	Flight Number	Departure Airport	Arrival Airport	Aircraft Registration Number	Aircraft Type	Event Summary	Investigating Country (Investigating Authority)	Official Investigation Report by Investigation	Status of Company-Internal Investigation Committee
2024/3/20	ANA	NH5	LAX	NRT	JA891A	B787-9	While approaching Narita Airport, the aircraft was struck by lightning near its nose. After coordinating repair methods with Boeing, the damage was determined to qualify as a major repair.	Japan JTSB	investigating	