Event Date	Operating Airline	Flight Number	Departure Airport	Arrival Airport	Aircraft Registration Number	Aircraft Type	Event Summary	Investigating Country (Investigating Authority)	Official Investigation Report by Investigating Authority Source: JTSB Homepage	Status of Company-Internal Investigation Committee
February 5, 2012	ANK	731	Itami	Sendai	JA8384		The aircraft took off from Osaka International Airport. When conducting a go-around during its approach to Runway 27 at Sendai Airport, the lower part of the rear fuselage made contact with the runway at around 09:03 JST, damaging the airframe. Thereafter, the aircraft landed at Sendai Airport at around 09:27 JST.	Japan JTSB	Report published on September 27, 2013	Investigation committee dissolved on October 1, 2013