

Event Date	Operating Airline	Flight Number	Departure Airport	Arrival Airport	Aircraft Registration Number	Aircraft Type	Event Summary	Investigating Country (Investigating Authority)	Official Investigation Report by Investigation	Status of Company-Internal Investigation Committee
January 25, 2023	ANA	8512	HKG	NRT	JA603A	B767-300	After landing at Narita Airport, when parking at Spot 222, the road surface was frozen and the aircraft slipped, and the front lower part of the aircraft came into contact with the parked main deck loader vehicle and stopped.	Japan JTSB	Report published on December 21, 2023	Monitoring the implementation status and effects of measures